





VYFLEX 198 Hyacinth

VYFLEX 624 Mulberry

VYFLEX 404 Henna



VyflexPlus pressure relief vinyl



Upholstery



Flame Retardant Multi-Directional To Crib 5



Stretch



Waterproof



& Anti Fungal



Anti Microbial Stain Resistant

yflexPlus Technical Information

Composition:

Coating: PVC/PU/Acrylic Basecloth: Cotton/Elastane

Weight:

760 a/m² +/-5%

Width:

140cm (55")

Flammability:

BS5852:2006 Ignition Source 5

EN1021-1/2 NFPA 260

Abrasion Resistance:

100.000+ Martindale rubs

Colour fastness to light:

Grade 4-5

Colour fastness to rubbing:

Wet 4, Dry 4

Features:

- Shield Plus Anti-Microbial and Anti-Fungal Protection Inc. C Diff Spore
- Scratch Resistant with colour solid through to the base cloth
- Multi-Directional Stretch for use in pressure relief seating
- Improved Stain Resistance with Acryltron

Vyflex Plus multi-directional stretch vinyl is recommended for use with the new generation of pressure relief foams to provide pressure relief seating within all healthcare environments: hospitals and care homes.

Recommended Cleaning:

- · Wipe clean regularly with a damp microfibre cloth and water to remove dust particles and prevent build up of soiling. Clean regularly with a damp cloth to remove dust particles and light soiling.
- Remove spillages promptly with an absorbent dry cloth.
- For general soiling, use a soft brush/microfibre cloth taking care to avoid abrasive damage to surface and use tepid soapy water (non-alkaline). Rinse clean with water and dry with an absorbent cloth.
- Bodily fluids should be removed promptly (within 15 minutes) with cold water and then cleaned as above.
- Extreme soiling/infection control purposes use a 5% sodium hypochlorite (bleach) solution, Haz Tabs or Chlor-Clean.
- Steam cleaning is an effective sanitizer (as are Haz Tabs and Chlor-Clean) but is not a good cleaner. Cleaning with a microfibre cloth and water is more effective. Steam and heat from steam cleaners actually seal in oily residues from bodily fluids, etc.

If steam cleaning is essential, use infrequently for emergency infection control purposes only and in accordance with the machine manufacturer's recommendations. As we are unable to comment on the variety of machines in the marketplace or on the operator's handling, care should be taken for the sake of both the upholstery fabric and the wooden frame and we are unable to guarantee these.

- Do not machine wash or dry clean.
- Do not use furniture polish, stain remover or solvents.
- Remove indigo dye from denim and canvas garments immediately. Dye/inks will produce permanent staining if not dealt with promptly.

Although every effort is made to ensure that fabrics ordered match the colours in this pattern card, slight variations may occur from batch to batch.

Please note Panaz reserve the right to update product specification at their discretion.



Head Office Panaz Ltd, Spring Mill, Fence, Near Burnley Lancashire. BB12 9HP England

Continuity:

Tel: +44 (0) 1282 696969 Fax: +44 (0) 1282 611519 email: admin@panaz.co.uk



For further information please visit www.panaz.com

Panaz France 7 rue Ferdinand Fabre, 75015 Paris (Métro Convention - Ligne 12) France Tel: +33 (0) 1 40 25 05 07

Fax: +33 (0) 1 40 25 09 64

email: patrick.martinez@noos.fr

Panaz Germany Nortzstrasse 20 67152 Ruppertsberg Germany

Tel: +49 6326 967 528 Fax: +49 6326 980 553 email: Uwe.Ney@t-online.de



Panaz (USA) Inc 2102 Business Center Drive Suite 215B Irvine, CA 92612 USA

Tel: +1 949 253 4163 Fax: +1 949 253 4167 email: sales@panaz.com